SPECIFICATIONS

Color Temperature: 3200 - 5600K

CRI ≥ 96


Luminous Flux: 1200LM Run Time: 1 Hour 30 Minutes LED Count: 180 Elements Power Consumption: 12W Battery capacity: 4400mAh

Weight: 6 ounces

Dims: L 5.9" x W 3.175" x .39" Mount: Cold Shoe 1/4-20 threads

Charge Method: USB

Mounting Holes Locations







Questions? Call Tech Support (973) 427-1160 8-5pm EST M-F email support@frezzi.com

This product has a warranty of 1 year from the date of purchase against defects in parts and labor.



7 VALLEY STREET HAWTHORNE, NJ 07506 USA HTTP://WWW.FREZZI.COM E-MAIL INFO@FREZZI.COM PHONE: (973) 427-1160 FAX: (973) 427-0934







Quick Start Guide



READ MANUAL PRIOR TO USE

Operation

Power

PRESS & HOLD 2 Seconds to TURN ON/OFF

Mode



PRESS to change from Color to Brightness Adjust

Adjust

PRESS to Increase Color Temp/Brightness

PRESS to Decrease Color Temp/Brightness



Control Buttons

LED OUTPUT OFF

PRESS and HOLD the MODE button for 2 seconds will make the brightness to 0%.

The unit will remain ON. Press + button To increase brightness



Charge Input

Use supplied USB charge cable with a USB compatible charger.

Internal Battery can be used at a USB POWER BANK with supplied FEMALE USB Adapter.



Mounting and Operation

Mounting to a Camera with Shoe




Screw SHOE MOUNT into a 1/4-20 hole on the bottom of Pocket Light.

TIGHTEN Locking wheel to secure.

Slide SHOE into CAMERA and TIGHTEN locking wheel to secure.

Smart Phone Kit Mounting OPTION




Mount Pocket Light to Phone Holder If using phone in "Selfie" style for a Skype interview, mount light the other way.

Mount phone by pulling open Phone Holder


Mount phone older to Tripod

Pull open Tripod Legs



Phone Holder opens to secure phone

Pull back rear leg



Close Tripod Legs to use as Handgrip